

4. Mechanical Sweeping

Operation and Site Condition: Small amounts of mud trapped in tire tread will spread dirt on the streets overtime and some dirt can migrate or be spread by various operations which is expected and need to be managed by the project manager.

Instruction: Sweeping must be done at the end of each work day or more as needed.

Schedule: Schedule upon need

Maintenance Requirements: Dirt and mud of levels beyond manual sweeping capabilities.

Maintenance Personnel/Training: Scheduled by the Project Manager. Project Manager is responsible for training all sub-contractors and trades to follow track out procedures. Not following track out procedures or contribute to sediment in the street or public right-a-way unnecessarily is subject to project shut down and or fines.

Detail: NA