

5. Hand Sweeping

Instruction: Square nose shovel and broom. Repeat removal until no more mud can be picked up. Do not worry about the dirt stain and **do not wash with water**. The small amounts of mud trapped in tire tread will also spread dirt on the streets overtime. In this case the mud must be removed by Mechanical Sweeping.

Scheduled: By the Project Manager

Maintenance: Scheduled by the Project Manager. Project Manager is responsible for training all sub-contractors and trades to follow track out procedures. Not following track out procedures or contribute to sediment in the street or public right-a-way unnecessarily is subject to project shut down and or fines.

Applicable Trades: All

Detail: NA